

Drivbiwire VNT15/17 repair procedure


Tools needed: T-20 Torx 10mm Box end wrench 17mm Box end wrench Steel Drift Heavy weight hammer High temperature (1700°F/ 930°C) or greater Pick Green Scotch-Brite Emery Cloth
























DO NOT hit the ALUMINUM!!! Verify with every hit you are on the cast iron bearing housing!!!





























DO NOT scratch or sand this area. Use Green Scotch-Brite to get carbon off face.



<text>























